

Previous CS-800 / CS-500 **Firmware version information**

V1.3.2

Bug Fixes

- Fixed the issue where the following occurred when the camera is switched during a Teams meeting:
 - Even though the microphone is muted (status indicator on CS-800/CS-500 is lit in red), audio may be picked up and output to the remote party.

V1.3.1

Improvements

- Improved camera image quality.
- Improved to reduce camera startup time when using Google Meet.

Bug Fixes

- Fixed the issue where the volume could not be changed with the remote control for a CS-800/CS-500 connected to a Mac.
- Fixed the issue where microphone noise may occur immediately after starting a meeting in Microsoft Teams.
- Fixed the issue where the Auto monitor off feature may be activated even though the camera detected a person.

V1.2.0

New Functionality

- CS Remote Configurator is now supported. Multiple CS-800 and CS-500 devices connected via Wi-Fi can be batch-configured.
 - Batch-updating firmware

- Batch-importing configuration files
- Batch-changing standby images
 - ※ In order to use CS Remote Configurator, update the device firmware to version 1.2.0 or later.
- Configuration files can now be imported/exported using Yamaha CS Manager.
- Using Yamaha CS Manager, host names can now be specified to identify multiple CS-800s and CS-500s.

Improvements

- Improved accuracy of face focus beamforming and improved sound quality.
- Improved self-silence function to help prevent the initial loss of human voices.
- Improved camera image quality.
 - Reduced noise
 - More natural sharpness adjustment
 - Improved color of people's faces
- Improved smart framing.
 - Improved accuracy of face detection
 - Improved speaker tracking speed in Speaker Tracking mode
 - Improved behavior in Individual mode when the designated speaker has left
- Fixed an issue where the camera picture would occasionally disappear.
- The specifications have been changed so that the time on the standby screen is hidden when the time is not synchronized with the NTP server.

Bug Fixes

- Fixed an issue where changes to the subnet mask setting by using Yamaha CS Manager was not reflected.
- Fixed an issue where an echo may occur immediately after starting a Bluetooth call.
- Fixed an issue where the speaker and microphone would not work if the device and computer are connected with a USB cable and both are left turned on for more than a month.
- Fixed other minor bugs.